Product Management Information



Published: Laetus Product Management 005/2020

Date: 29 June 2020


 X
 Customer Information
 New Product
 System

 Internal Information
 X
 Product Change
 Software

 Technical Information
 X
 Ordering
 Accessories

PHARMA-CODE Scanner COSI 221 – Announcement of Discontinuation

This document provides the announcement for the upcoming discontinuation of COSI 220/ 221 PHARMA-CODE reading technology. After more than 25years of using the COSI 22x technology, Laetus must announce the production stop.



| Life Cycle Phase | COSI 221 / iBox COSI New installations | COSI 221 / iBox COSI Individual Product Supply |
|---|--|---|
| Discontinuation Announcement (this document) | 29 th of June 2020 | |
| Last Quotes for new projects | 30 th of June 2020 | Individual agreement to be agreed with local Laetus sales contact |
| Start of Limited Lifecycle Services (last shipment) | 1 st of July 2020 | |
| End of Individual Product Supply | n/a | 30 th September 2020 |
| End of Patch support | 30 th of June 2023 | |
| End of Service / Spare Parts | 30 th of June 2025 | |

Description of related Product Life Cycle Phases:

Discontinuation Announcement

(This document)

- Informs about upcoming end of production
- Introduction of alternate solutions

Individual Product Supply

Page: 1 - 3 File: Laetus PMI 2020-005 COSI221 DiscontinuationAnnouncement

Product Management Information



- Agree during Discontinuation Announcement Phase
- Continue of individual shipping during Limited Life Cycle Services

Limited Lifecycle Services

- End of shipments
- Max. 3 years support for software patches
- Min. 5 years spare parts and field service available after end of production

COSI 221 Technology – Devices to be discontinued

The below table lists all components affected by discontinuation.

| COSI 221 Technology Article | Article No. | Notes |
|---|-------------|--|
| Scanning head COSI 221-01, set | LT209913520 | See alternate solutions for replacement |
| Scanning head COSI 221-01 | LT209913514 | |
| iBox COSI 221 V3 | LT139830020 | |
| Bracket for COSA/COSI on a GUK folding machine, bottom side reading | LT659920030 | Refer to VI configuration for use with alternate devices |
| Carton flap guide for one-track code on cartons, COSA/COSI 221 | LT659920025 | Refer to VI configuration for use with alternate devices |
| Reflector with adaptor bracket for carton flap COSA/COSI 221 | LT657740003 | |
| Prism for COSA/COSI for 90° reading | LT207743502 | |
| Connecting cable 2.5m for COSI 221 / CORICAM, with straight connector to ARGUS 601x / iBox | LT207939183 | |
| Connecting cable 7m for COSI 221 / CORICAM, with straight connector to ARGUS 601x / iBox | LT207939184 | |
| Connecting cable 10m for COSI 221 / CORICAM, with straight connector to ARGUS 601x / iBox | LT207939186 | |
| Connecting cable 7m for COSI 221 / CORICAM, with 90° angled connector to ARGUS 601x and iBox | LT207939188 | |
| Connecting cable 10m for COSI 221 / CORICAM, with 90° angled connector to ARGUS 601x and iBox | LT207939189 | |
| Mounting angle COSI | LT207711173 | |

Supporting article from external suppliers, discontinued with immediate effect 1st of July 2020

| COSI 221 3 rd Party Article | Article No. | Notes |
|--|-------------|-------|
| Divert sheet metal with two windows | LT659791000 | |
| for FA 21 (GUK) | | |

Page: 2 - 3 File: Laetus_PMI_2020-005_COSI221_DiscontinuationAnnouncement



COSI 221 Technology – Spares and repair analysis

Short summary of availability of repairs and exchanges.

Exchange article:

| Description | Article No. | State |
|---|-------------|---------------------|
| Scanning head COSI 221-01 | LT209913514 | Limited |
| iBox COSI 221 V3 | LT139830020 | Currently unlimited |
| Carton flap guide for one- track code on cartons, COSA/COSI 221 | LT659920025 | Currently unlimited |
| Reflector with adaptor bracket for carton flap COSA/COSI 221 | LT657740003 | Currently unlimited |
| Prism for COSA/COSI for 90° reading | LT207743502 | Currently unlimited |
| Mounting angle COSI | LT207711173 | Currently unlimited |
| Cables | Various | Currently unlimited |

Repairs:

| Description | State |
|---|---------------------|
| Exchange of COSI 221 flex circuit board | Limited |
| Exchange of housing / lens | Not available |
| LED exchange | Currently unlimited |
| Calibration / Functional test | Currently unlimited |

COSI 221 Technology – Available replacing solutions

Please contact you local Laetus supplier for solution based on our well introduced LLS wt580 or COCAM wt880 scanners.